

# Motors – Main Drive

\*Exchange Core

\*Electrical Sensitivity

## 10x15 – Windmill



10x15 Platen with or without Variable Speed Pulley  
110 / 220 / Single Phase  
220 / 380 / 3 Phase

## 13x18 – Windmill



110 / 220 / Single Phase  
220 / 380 / 3 Phase

## TOK / TOM



#22.101.1311

## Quickmaster



#22.101.1311

## K-Offset K-Letterpress



with or without Variable Speed Pulley  
220 / 380 3 Phase

## S-Letterpress / Diecutters



2 belt – 2 Speed Pulley  
S28 / SB / SBG  
220 / 380 / 3 phase



3 Belt Single Pulley  
230 / 380 / 415  
SBB



SBD Diecutter  
230 / 380 Volt 3 ph.  
Servo Motor type


## S-Offset – 1 Color



SORK  
SORM  
SORD  
SORS

Call

## S-Offset – 2 Color




Surplus Motors?  
Please Call Us



SORD/Z  
SORS/Z

## GTO 1/C



Surplus Motors?  
Please Call Us

#69.101.XXX

## GTO Z/P



#52.101.XXX Single Speed  
#79.101.XXX Servo type

## GTO V/P



#62.101.XXX Single Speed  
#89.101.XXX Servo type

## GTO F/P



#98.101.XXX

## MOZ/S




#53.101.2003 / CpTronic  
#53.101...10 preCpT

## MO VPH



#63.101.2004 CpTronic  
#92.101...1 PreCpT

## MOF/P/S/H



Surplus Motors?  
Please Call Us

#92.101.2004 CpTronic  
#92.101...1 PreCpT

## 72 Z/P




#83.101XXX

## 72 / 102 / ZP / Speedmaster



#91.101.10...


## 102V / 72V



Surplus Motors?  
Please Call Us

#71.101...1

## 102F/S



Surplus Motors?  
Please Call Us

Call



Visa



MasterCard

Call Demers Parts Hotline @ 1-800-956-3612 ■ 727-372-1200