

# Ink Distributor Rilsan – Geared Drive

## Rilsan – Geared Distributor Cylinder – (removeable by Heidelberg tool\*)

Note: Washup Blade Contacts When Washing Up

SORK / SORKZ #58.009.015F  
 SORM / SORMZ #68.009.015F  
 SOR / SORZ #66.009.015F  
 SORD / SORDZ #76.009.015F  
 SORS / SORSZ #41.009.015F  
 (All both unit #1, #2)



\*Heidelberg Removal Tool  
 (supplied with original press)  
 #66.024.002



Operator Side View

72 Speedmaster  
 #68.009.015F



Early 102 Speedmaster  
 #41.009.015F 1060 mm  
 #71.009.015F



Drive Side View

## Rilsan – Distributor – Geared – removed by 3 bolts, each side

Note: No Washup Blade Contact

GTO46  
 #42.009.015F – #GTO 0915–  
 60mm (dia.) x 467mm  
 (18 3/8") (length)



GTO52  
 60mm (dia.) x 516mm  
 (20 5/16") (length)  
 #69.009.016F

#42.009.016F – #GTO 0916 –  
 60mm (dia.) x 456mm  
 (17 15/16") (length)



SM74  
 #M2.009.015  
 #M2.009.023F

MO-Offset  
 W/O CPC #43.009.015F –  
 39mm (dia.) 1 17/32"  
 W/CPC #63.009.015F  
 #43.009.016F – 39mm (dia.)



SM72  
 #68.009.016F



SM102 #41.009.016F  
 w/ or w/o both journal ends

## Rilsan ... (removed only by 3 allen bolts or 3 hex head bolts each side)

Washup Rubber Blade Contacts when washing ink



GTO46  
 60mm (dia.) x 467mm (18 3/8") (length)  
 #42.009.015 #GTO 0915



GTO52  
 60mm (dia.) x 537mm (21 5/32") (length)  
 #69.009.015F



MO #43.009.015F  
 675mm



SM74 Assembly Ink Distributor  
 #M2.009.025



Visa



MasterCard

Call Demers Parts Hotline @ 1-800-956-3612 ■ 727-372-1200